


hm

|  |  |   |                             |  |  |
|--|--|---|-----------------------------|--|--|
|   |  | <b>POTENTIAL HAZARDOUS WASTE SITE<br/>IDENTIFICATION AND PRELIMINARY ASSESSMENT</b> |                             | <b>REGION</b><br>6                     | <b>SITE NUMBER (to be assigned by HQ)</b><br>TXD 980 878 789 |
| <b>NOTE:</b> This form is completed for each potential hazardous waste site to help set priorities for site inspection. The information submitted on this form is based on available records and may be updated on subsequent forms as a result of additional inquiries and on-site inspections.   |  |   |                             |  |  |
| <b>GENERAL INSTRUCTIONS:</b> Complete Sections I and III through X as completely as possible before Section II (Preliminary Assessment). File this form in the Regional Hazardous Waste Log File and submit a copy to: U.S. Environmental Protection Agency; Site Tracking System; Hazardous Waste Enforcement Task Force (EN-335); 401 M St., SW; Washington, DC 20460. |  |   |                             |  |  |
| <b>I. SITE IDENTIFICATION</b>  |  |   |                             |  |  |
| <b>A. SITE NAME</b><br>Underground Gasoline Leak   |  | <b>B. STREET (or other identifier)</b><br>1240 N. 5 <sup>th</sup> Street            |                             |  |  |
| <b>C. CITY</b><br>Silsbee  |  | <b>D. STATE</b><br>Texas  | <b>E. ZIP CODE</b><br>77656 | <b>F. COUNTY NAME</b><br>Hardin County |  |

A preliminary assessment form 2070-2 was not completed for this site. However, a Record of Communication was completed on 08/30/84 and includes information which would have been covered in a preliminary assessment of the site.

David Gonzalez. GH-  
11/05/87.

SUPERFUND FILE

90067518



DEC 29 1992

REORGANIZED

T-878905-P4